

Product Technical Update

Equinox Front & Rear Monitors

Equinox touch screen new PN # 910T0043-505

Explanation

Equinox tools were built with touch screen monitors. The front monitor contained a 486 Pentium as the main computer. The 486 is no longer supported by the manufacturer and will be replaced with Pentium III computers. This upgrade necessitates new software and wiring changes.

Additional Changes

The new front monitor is an ELO flat panel display. (See photo at right). There is no longer a powercard contained within the monitor so a UPS (uninterrupted power supply) must also be installed. This will allow the monitor to continue operating in the event of power loss to the tool. All stored settings and teach points will be retained. The software and wiring changes to the front monitor require that the rear monitor be replaced as well. *(The old monitor will not work with the software changes).* Additionally, if the power supply on the rear monitor is not **PN # 73147-56** it will have to be replaced during this upgrade.



Equinox touch screen monitor

Customers should contact Rhotech Technical Support to help prepare a formal quote.

