

Product Technical Update

SST/SAT Touch Screen Upgrade

Touch Screen PN # 73301-20A is no longer available.
This is replaced with a new design
PN # 73301-101M in assembly PN # 901U0055-01.

Explanation

Class 1 SSTs and SATs were built with touch screen PN # 73301-20A (See photo on right). No longer being supported by the manufacturer, this part has become obsolete. The new touch screen PN #73301-101M is part of assembly PN # 901U0055-01. (See photo lower right). This upgrade will also require new software installation and some wiring changes.

Additional Changes

Spray Acid Tools (SATs) will need the new software and wiring to replace the old monitor. Spray Solvent Tools (SSTs) will also require a new stainless steel front panel with the installation of the new touch screen.

Customers should contact Rheteck Technical Support to help prepare a formal quote.



Original SST/SAT monitor PN # 73301-20A.
has become obsolete.



New flat panel touch screen monitor replaces
PN # 73301-20A monitor.
(PN # 73301-101M , assembly PN # 901U0055-01)

Reference : Semitool Technical Service Bulletin # 520

